



AV-30-C

STC Service Bulletin

Software Upgrade to 3.0.1



© 2021-2024 uAvionix Corporation. All rights reserved.

uAvionix Corporation
Bigfork, MT

www.uavionix.com
support@uavionix.com

Except as expressly provided herein, no part of this guide may be reproduced, transmitted, disseminated, downloaded, or stored in any storage medium, for any purpose without the express written permission of uAvionix. uAvionix grants permissions to download a single copy of this guide onto an electronic storage medium to be viewed for personal use, provided that the complete text of this copyright notice is retained. Unauthorized commercial distribution of this manual or any revision hereto is strictly prohibited.

uAvionix® and Ping® are registered trademarks of uAvionix Corporation and may not be used without express permission of uAvionix.

AV-30, AV-30-E, AV-30-C, AV-Mag, AV-Link, BeaconX, tailBeaconX, and skyBeaconX are trademarks of uAvionix Corporation and may not be used without express permission of uAvionix.

Patent uavionix.com/patents

1 Revision History

Revision	Date	Comments
A	11/12/2024	Initial release

2 Warnings / Disclaimers

uAvionix is not liable for damages arising from the use or misuse of this product.

This equipment is classified by the United States Department of Commerce's Bureau of Industry and Security (BIS) as Export Control Classification Number (ECCN) 7A994.

These items are controlled by the U.S. Government and authorized for export only to the country of ultimate destination for use by the ultimate consignee or end-user(s) herein identified. They may not be resold, transferred, or otherwise disposed of, to any other country or to any person other than the authorized ultimate consignee or end-user(s), either in their original form or after being incorporated into other items, without first obtaining approval from the U.S. government or as otherwise authorized by U.S. law and regulations.

3 Contents

1	Revision History.....	3
2	Warnings / Disclaimers	4
3	Contents	5
4	Tables.....	6
5	Planning Information.....	7
5.1	Distribution / Eligibility.....	7
5.2	Applicability.....	7
5.3	Description.....	8
5.4	Time Required	8
5.5	Weight and Balance.....	8
5.6	Electrical Load Data.....	8
5.7	Applicable Publications.....	8
6	Required Items	9
6.1	Windows PC with Serial Port	9
6.2	AV-Link.....	10
7	Update Notes.....	10
8	PC Serial Update.....	12
8.1	Serial Update Preparation.....	12
8.2	Serial Update Procedure	12
9	AV-Link Update.....	17
9.1	AV-Link Update Preparation	17
9.2	AV-Link Update Procedure	17
10	Post-Accomplishment Verification and Actions	21
10.1	Verify Update Versions	21
11	System Checkout.....	22
12	Support.....	23

13 Maintenance Record.....24

4 Tables

Table 5-1 Applicability.....7
Table 5-2 AV-30-C Documents8
Table 6-1 Software Update Files.....9

5 Planning Information

5.1 Distribution / Eligibility

The Accomplishment Instructions contained in Section 10 may only be performed by appropriately authorized personnel.

5.2 Applicability

This Service Bulletin applies to AML STC SA00410BO for the uAvionix AV-30-C UAV-1003429-001, UAV-1003429-002, and UAV-1003429-003 with operating software release 2.5.0 or earlier. Use Table 5-1 Applicability to determine applicability of the software update.

Table 5-1 Applicability

Hardware P/N Marking	Applicability
UAV-1003429-001	Verify by procedure
UAV-1003429-002	Verify by procedure
UAV-1003429-003	Verify by procedure

Parts identified above as “Verify by procedure” may have software release 2.5.0 or previous installed. To determine what version of software is installed:

1. Push and hold center rotary knob while powering up unit.



2. Once the uAvionix startup screen displays you can release.
3. Push left button under the MENU until the “INSTALL / ROT TO SEL” appears.

4. Rotate knob until you see “SW VERSION”
5. If the version displayed is 2.5.0 or earlier proceed with this Service Bulletin.

5.3 Description

This Service Bulletin provides instructions for loading uAvionix AV-30-C UAV-1003429-001, UAV-1003429-002, and UAV-1003429-003 with updated software release 3.0.1.

Pitot and static pneumatic lines must be connected if not already connected. This Service Bulletin does not describe or provide authority for that work.

5.4 Time Required

For field software update, up to 90 minutes is required to perform this update procedure. Additional time and approval may be required if pitot and static connections are not installed.

5.5 Weight and Balance

No change.

5.6 Electrical Load Data

No change.

5.7 Applicable Publications

The following documents are applicable to the software release 3.0.1.

Table 5-2 AV-30-C Documents

Title	Part Number	Revision
AV-30-C Installation Manual	UAV-1003947-001	P
AV-30-C Pilot’s Guide	UAV-1003946-001	I

6 Required Items

There are two methods available to perform the update. The first involves a Windows PC and serial port, the second uses the optional AV-Link device over Wi-Fi.

Both methods require you to download the software update file below.

Table 6-1 Software Update Files

Filename	Version	SW Part Number	Checksum	SHA1 Hash
UAV-1003494-008-av30c-3_0_1-75cd8fd.bin	3.0.1	UAV-1003494-008	0xA3388C40	7472bb28dee2 ece2acc1d783 98e064e33c21 170e

uAvionix software update files are available for download from the uAvionix Support website at no charge, at:

<https://uavionix.com/av-30-c-service-bulletin-software-upgrade-3-0-1/>

Click on the link in the section **AV-30-C v3.0.1 Firmware** and save it to your PC or mobile device.

Ensure the software and any necessary update tools have been downloaded prior to visiting the aircraft. An internet connection is required to download the software and application. An internet connection is not required to perform the update.

6.1 Windows PC with Serial Port

The following items are required to perform the update when using a Windows PC with serial cable:

Quantity	Description
1	Windows PC running Windows 7 or later
1	Available serial port or appropriate USB to RS-232 converter Examples: FTDI, Parallax 28030, Sabrent CB-8P6F or similar
1	Female DB-9 with solder or crimp terminals
2	Female terminals suitable for the installed DB-15
4'	22-24 AWG wire
1	uAvionix AV Update Tool for Windows (UAV-1005199-001)
1	AV-30-C Software as shown in Table 6-1 Software Update Files.

The uAvionix AV Update Tool is available on the website linked above in the section **AV Update Tool**. Download it to your PC.

6.2 AV-Link

The following items are required to perform the update when using AV-Link over Wi-Fi:

Quantity	Description
1	PC or mobile device
1	uAvionix AV-Link-E (UAV-1004413-001) or AV-Link-C (UAV-1004414-001) running software version 0.3.5 or later.
1	AV-30-C Software as shown in Table 6-1 Software Update Files.

AV-Link-C (certified) or AV-Link-E (experimental) may be used to perform this service bulletin. If using an AV-Link-E, the AV-Link-E must be removed from the aircraft upon completion of the service bulletin.

AV-Link software version 0.3.5 is required. If using an AV-Link with version 0.3.4 or earlier, please upgrade your AV-Link prior to performing this service bulletin.

uAvionix provides software update files for download from the uAvionix Support website at no charge.

For AV-Link-C, follow the instructions in AV-Link-C Service Bulletin Upgrade to 0.3.5 UAV-1008457-001 Rev A.pdf, available at:

<https://uavionix.com/av-link-c-service-bulletin-software-upgrade-0-3-5/>

For AV-Link-E, follow the instructions in AV-Link-E Service Bulletin Upgrade to 0.3.5 UAV-1006731-006 Rev A.pdf, available at:

<https://uavionix.com/av-link-e-service-bulletin-software-upgrade-0-3-5/>

7 Update Notes

AV-30-C configuration settings will be preserved during the update procedure when possible. However, please take note of all settings before

performing the update, and verify settings are correct after the update has been applied. Additional configuration settings have been added. See the installation manual for details for each setting.

If pitot and static lines were not previously connected, ensure appropriate approval and connect the lines now to ensure full performance and functionality.

Ensure you are running a previous version of AV-30-C software. Specifically, your AV-30-C should currently be running 2.5.0 or earlier.

There are two approved methods for updating the AV-30-C. The AV-30-C can be updated using either a traditional direct serial connection or using the AV-Link to update the AV-30-C via wireless interface. Either method is suitable, and the choice can be made according to installer preference or equipment availability. If the AV-Link installation is not approved, it must be used only for the update and removed after.


If performing the update using PC serial connection, proceed to §8 PC Serial Update.

If performing the update using the AV-Link, first verify that it is running software version 0.3.4 or later then proceed to §9 AV-Link Update. If the AV-Link is running version 0.3.4 or earlier, update the AV-Link to version 0.3.5 before proceeding. Refer to section 6.2 for links to AV-Link version 0.3.5 upgrade files.

8 PC Serial Update

8.1 Serial Update Preparation

1. Add wires to pins 8 and 15 to the AV-30-C harness if not already connected. Add an additional ground wire to either existing the ground from the AV-30-C harness or ground the new wire directly to aircraft ground.
2. Connect the new wires to the DB-9 connector as shown below. Upon completion of wiring, connect the new assembly to an available serial port or USB serial adapter.




Note: AV-Link must not be installed if performing an update using the PC serial update procedure.


8.2 Serial Update Procedure

1. Connect the AV-30-C to the Windows PC through the DB-9 connection previously installed in Section 8.1.


2. Apply power to the AV-30-C. Do not interrupt power during the update process.
3. Launch the previously downloaded AV Updater application.
4. On the AV Updater tool, select the appropriate COM Port from the dropdown menu and click “Connect”.



5. Proper connection has been made when the message “Unit Detected” has appeared on the bottom left corner of the AV Updater Tool. The screen on the AV-30-C will go black for the remainder of this procedure. If “Unit Detected” does not appear, contact uAvionix Support for additional guidance.
6. Once proper connection has been made, select the software file to upload to the AV-30-C by clicking “Open File” and selecting the previously downloaded software file as identified in Table 6-1 Software Update Files. A confirmation dialog will appear with the filename and a calculated SHA1 hash. To confirm integrity of the file, compare the displayed SHA1 hash to that in Table 6-1 Software Update Files. Note that the hash is not case sensitive.



7. When confirmed, press OK and the main dialog will re-appear.



8. Select “Write Firmware” to begin the upload.



DO NOT POWER OFF THE AV-30-C OR CLOSE THE UPDATER TOOL UNTIL THE UPDATE IS COMPLETE.




Figure 8-1 AV Update Tool

9. When the AV Update Tool displays “100%” and the lower status reads “Update Complete” the process is complete.
10. The unit will automatically restart. Upon restart of the unit, verify the startup screen indicates the updated software version.



THE SCREEN OF THE AV-30-C WILL GO BLACK WHILE THE DEVICE REBOOTS, THIS BEHAVIOR IS NORMAL AND THE STARTUP SCREEN WILL APPEAR AFTER REBOOTING.

11. If the unit was removed to perform the update it can now be reinstalled as per the installation manual.

12. Any new wiring added for the update process should be properly secured.
13. Following the completion of update, follow Section 10 to perform required post-installation procedures.

9 AV-Link Update

The AV-Link is a wireless bridge that extends the functionality of the AV-30-C. One of the functions AV-Link provides is the ability to update software on the AV-30-C through a web interface.

9.1 AV-Link Update Preparation

If AV-Link is already installed in the aircraft, proceed to Section 9.2.

If AV-Link is available but not installed, follow the installation procedure as described in AV-30-C Installation Manual UAV-1003947-001 Rev P (or latest available), Section 10.1 for the AV-Link-C.



Note: The AV-Link-E is not authorized for installation and use with AV-30-C other than installing software updates for certified aircraft. It must be removed before flight.


9.2 AV-Link Update Procedure

After the AV-Link and AV-30-C have been installed, AV-30-C software updates can be performed using the AV-Link web interface. The web interface is accessible through any PC or mobile device. Ensure the PC or device has the AV-30-C software noted in Table 6-1 Software Update Files downloaded and available before traveling to the aircraft site.

The following instructions show the update procedure when using a Windows PC. Apply the same procedures, modified as necessary, when using an alternate installation PC or device.

1. Apply power to the AV-30-C and AV-Link. Do not interrupt power during the update process.

2. Connect a PC to the AV-Link Wi-Fi Network. This will be displayed as AV-#### where #### will be 4 random characters ranging from 0-8 and A-F.




3. In a Web Browser (such as Google Chrome) navigate to the AV-Link home page via the following URL:


<http://192.168.5.1>

A page like the one shown on the right should appear.

4. At the bottom of the page select *AV Display Software Update*



5. On the AV Display Software Update page select *Choose File* then select the previously downloaded AV-30-C software.



AV Display Software Update


[Advanced](#)

Choose File No file chosen



[Home Page](#)


6. Once the file has been selected you will be asked to confirm the installation of the selected file. Press *OK* to proceed.



[Advanced](#)


[Home Page](#)

The screen on the AV-30-C will go black during the update. DO NOT power off the unit or close the web browser until the update is complete. The AV-30-C will restart when complete and the AV-Link will notify that the update is complete. Click OK.



Hardware part number UAV-1003429-001
 Software part number UAV-1003494-008
 Software version 3.0.1
 Software type Certified

- Power cycle the AV-30 and AV-Link. Again, navigate to 192.168.5.1. Verify that the new version (3.0.1) is now displayed.



10 Post-Accomplishment Verification and Actions

10.1 Verify Update Versions

On restart, verify that the startup screen displays the correct version number. Access the Installation Menu to complete post-accomplishment verification steps.

1. To enable access to the Installation Menu, ensure the unit is completely turned off. Push and hold the main control knob in while power is applied.



2. Keep the knob pushed until the startup screen displays, and then release.
3. Ensure the unit is in AI or DG mode; select the mode by pushing and holding the center button until the mode display changes.
4. In AI or DG mode, push the left button under the MENU until the "INSTALL / ROT TO SEL" appears.



5. Rotate the knob until you see “SW PART NUM”. Confirm part number matches that shown in Table 6-1 Software Update Files.
6. Rotate the knob until you see “SW VERSION”. Confirm version matches that shown in Table 6-1 Software Update Files.
7. Rotate the knob until you see “SW CHECKSUM”. Confirm checksum matches that shown in Table 6-1 Software Update Files. Note that the checksum is not case sensitive.

If all software fields match, continue with these instructions. Otherwise, contact uAvionix Support.

11 System Checkout

Perform the System Checkout procedure as described in “AV-30-C Installation Manual” UAV-1003947-001 Rev P Section 12.2 prior to returning to service.

Version 2.4.1 and greater uses pitot-static data to assist the attitude algorithm. Performing the **Air Data – Pitot Zero** procedure found in the Installation Manual is particularly important.

Version 3.0.1 and greater use updated gyro algorithms that require the **Gyro Calibration** procedure found in the installation manual to be performed.

12 Support

For additional questions or support please visit:

<http://www.uavionix.com/support/>

13 Maintenance Record

When post-accomplishment verification and system checkout is completed, make appropriate entries in the Aircraft Maintenance Log Book.

Maintenance Record

Service Bulletin UAV-1005689-007 Rev A to install software v3.0.1 for AV-30-C UAV-1003429-(____), AML STC SA00410BO, has been complied with.



A copy of this form must be submitted by visiting:

<https://uavionix.com/logbook/>

Date:	By:
Aircraft Information	
Make:	Model:
Serial Number:	Registration Number:
AV-30-C Information	
Serial Number:	
Hardware Part Number:	UAV-1003429-_____
Customer Information	
Name:	
Email:	
Telephone:	